



3D PRINTER

DATE: 04/19/18
PAGES: 1

FILE NAME: OQD08018.doc
REVISION : A

TITLE: How to export CWS file? Tick the Export to CWS Box.


INITIATE BY: Mikey
APPROVED BY: Manolo Chen

1.0 Purpose

Some customer can not Export CWS file through Creation workshop. The D7box/ D7plus screen show 0 layers all the time.

To remind D7 box and D7 Plus users that to tick the box in CW.

Note: Very common mistake by most of Duplicator 7 users who uses box or D7 Plus that they forget to tick the export to cws box in Creation workshop and wonder why the build plate does not move and why the printer does not work. Here is the Trick.




2.0 Scope


This document covers D7 box and D7 Plus.

3.0 Tick the box in Creation Workshop

Make sure tick the Export CWS box in CW(**Configure-Configure Slicing Profile-Export Slices to CWS**) and also make sure you see waiting message in the box. If you do not see it that means file has issue.



Note: Another very obvious sign that to know the slicing process was properly done is right after press the Play button on the box the UV light turns on and if you hold your hand on the back of the printer you'll see the light reflection. If there is no then your sliced model has issue.



3.0 Initiate by Mikey 19th April 2018