



3D PRINTER

DATE: 19/04/17
PAGES: 2

FILE NAME: OQD08008.doc
REVISION : A

TITLE: How to bypass fuse of LCD driving board?

INITIATE BY: Manolo Chen
APPROVED BY: Gary Chen

1.0 Purpose


The LCD driving board has no LED light and response to the motherboard. The static electricity would burn the fuse of LCD driving board. By bypassing the fuse would fix this issue.

2.0 Scope

This document cover Duplicator 7, V1.0 and V1.2

3.0 To bypass the fuse.

3.1 The FPI(N) is the fuse. Bypass this fuse(N) would light up the board again



4.0 Revisions

A – Initiate: 19/4/17 by: Manolo