



# 3D PRINTER

DATE: 01/16/18  
PAGES: 3

FILE NAME: OQD09003.doc  
REVISION : A

TITLE: i3 mini firmware flash

INITIATE BY: Mikey  
APPROVED BY: Gary Chen

## 1.0 Purpose

This file walks your through flashing i3 mini firmware.

## 2.0 Scope

This document covers i3 mini

## 3.0 Connect the Printer to PC via USB cable.

Connect your printer to your PC via USB cable and turn on the printer.


## 4.0 Download the hex file

First download the hex file from the link below;


<https://www.dropbox.com/s/o7rh20wt4ke1edr/i3mini-wanhao-v1.3.hex?dl=0>

## 5.0 Machine setting




5.1 Set the serial port on whatever your PC recognizes and baudrate on 250000 then click on OK.



5.2 Go to the Machine menu and click on Install custom Firmware.




5.3 Choose the hex file where you have saved it and click on OK. Uploading firmware starts and it takes few seconds then click on OK.



6.0 Note  
Initiate by Mikey on 16<sup>th</sup> Jan 2018.

During uploading firmware the screen goes blank, Please wait for few seconds.



Wait until the Wanhao Logo and home screen comes up.



**PRINTER IS READY TO USE**